

<i>Item/Location</i>	<i>Barrier (noted feature, item or area does not meet the new construction criteria detailed below)</i>	<i>Action</i>	<i>Priority</i>	<i>Target Date</i>	<i>Estimated Cost</i>	<i>Interim Solution</i>	<i>Action Completion Date</i>
01-Parking, General: No On-Site Parking, General Parking to the West.			1	2014 - 2015	\$0.00		
02-Walks and Sidewalks: From the General Parking Area to the Storage Area.			2	2014 - 2015	\$0.00		
03-Walks and Sidewalks: Dirt Walk in Front of Storage Units.	Continuous common surface is not interrupted by steps or abrupt changes in level (less than 1/4" vertical or 1/2" beveled at 1:2).	Minor asphalt overlay (1" avg. or less). Pave a section in front of both kinds of units for access to Units #628 and #630 (photo #7).	1	2014 - 2015	\$3,207.73		
<b>Report Year 2015 - 2016 Total</b>					<b>\$3,207.73</b>		
<b>Entire Report Total</b>					<b>\$3,207.73</b>		