

<i>Item/Location</i>	<i>Barrier (noted feature, item or area does not meet the new construction criteria detailed below)</i>	<i>Action</i>	<i>Priority</i>	<i>Target Date</i>	<i>Estimated Cost</i>	<i>Interim Solution</i>	<i>Action Completion Date</i>
01-Site Entrance Signage: South Side of Fire Station #2. [One compliant entrance sign at the head of the Van Accessible handicap parking space in Item #3. Fill in the phone number of the local law enforcement agency at the bottom of the sign.]	Warning signage contains appropriate wording and information.	Apply required phone number to sign in minimum 1" high numbers.	1	2015 - 2016	\$53.60		
02-Parking, General: South Side of Fire Station #2. [Five total parking spaces including one Van Accessible handicap parking space.]			1	2015 - 2016	\$0.00		
03-Van Accessible Parking Space: South Side of Fire Station #2. [One Van Accessible handicap parking space.]	2% max. surface slope within parking space & access aisle.	Replace concrete. Install striping and surface identification for Van Accessible stall.	1	2014 - 2015	\$3,644.45		
04-Walks and Sidewalks: South Side of Fire Station #2. [From the Van Accessible handicap parking space in Item #3 to the South entrance into the Fire Station.]			2	2014 - 2015	\$0.00		
05-Doors: South Entrance to the Fire Station. [One single door.]			2	2014 - 2015	\$0.00		
06-Clear Space at Doors: South Side of Fire Station #2. [One single door.]	Floor or landing is level and clear (2% max. slope).	Install level exterior door landing.	2	2014 - 2015	\$1,531.28		
Report Year 2015 - 2016 Total					\$5,229.33		
Entire Report Total					\$5,229.33		