

City of Paso Robles – DPW 17-17  
West Side Slurry Seal Project



Looking east from Merry Hill



Looking east from Merry Hill

12<sup>th</sup> Street – Fresno to Merry Hill

Paving repair has been completed, and the contractor is finishing up with raising the utility covers and placing the AC Berms along the sides to control the drainage (9-7-2018).

City of Paso Robles – DPW 17-17  
West Side Slurry Seal Project



Looking west from Fresno



Looking west from Fresno

12<sup>th</sup> Street – Fresno to Merry Hill

Paving repair has been completed, and the contractor is finishing up with raising the utility covers and placing the AC Berms along the sides to control the drainage (9-7-2018).